
5 W FLASH REPORT

Temporary entrance closure

Initial notification / 18/11/2026 / 08:10 local



Red marks the reported repair area at the delivery entrance.

WHO	The site team notified the duty coordinator. Two delivery crews were booked to use the entrance.
WHAT	Surface repairs temporarily closed the entrance to incoming vehicles.
WHEN	The closure began at 08:00 on 18/11/2026. The next update was due at 10:00.
WHERE	The delivery entrance shown on the map. The closure applies to that access point.
WHY	The contractor needed the carriageway clear while the replacement surface set.

DUTY ACTION

Confirm the next delivery slot with reception before dispatch.